



**Midwest Sustainable Energy Contractors, Inc.**


1010 32 Ave A  
Moline, Illinois  
61265

309.764.1111

**Water Leakage Detection Demo  
Document**


---

---




**IR000003 - Copy.IS2**

1/1/2008 7:15:22 PM



**IR000003.IS2**

1/1/2008 7:15:22 PM



**IR000003 - Copy - Copy.IS2**

1/1/2008 7:15:22 PM




**IR000004.IS2**

1/1/2008 7:19:14 PM




**IR000005.IS2**

1/1/2008 7:20:10 PM




**IR000006.IS2**

1/1/2008 7:21:22 PM




**IR000007.IS2**

1/1/2008 7:29:18 PM




**IR000008.IS2**

1/1/2008 7:45:41 PM




**IR000009.IS2**

1/1/2008 7:46:02 PM




**IR000010.IS2**

1/1/2008 7:48:24 PM




**IR000011.IS2**

1/1/2008 7:50:41 PM



**IR000012.IS2**

1/1/2008 8:01:19 PM




**IR000013.IS2**

1/1/2008 8:10:50 PM




**IR000014.IS2**

1/1/2008 8:11:37 PM




**IR000015.IS2**

1/1/2008 8:17:10 PM




**IR000016.IS2**

1/1/2008 8:28:53 PM




**IR000017.IS2**

1/1/2008 8:30:07 PM




**IR000018.IS2**

1/1/2008 8:39:25 PM




**IR000019.IS2**

1/1/2008 8:53:48 PM




**IR000020.IS2**

1/1/2008 8:54:38 PM




**IR000021.IS2**

1/1/2008 8:57:41 PM



**IR000022.IS2**

1/1/2008 9:24:16 PM



**IR000023.IS2**

1/1/2008 9:24:41 PM